



ISO 17020
ACCREDITED
INSPECTION
N° 103

S&A Quality Assurance Surveyors Scope of Accreditation

Contact person	Emmanuel Scerri
Address	S&A Quality Assurance Surveyors Ltd., 142 'Matarieh', Nazju Ellul Street,
Telephone	+356 99469994
Fax	+356 21314593
Email	scerrie@maltanet.net
Website	N/A

ACCREDITATION INFORMATION - INSPECTION BODY

Accreditation No.	103
Accreditation Certificate No.	103/1
Accredited according to	MSA EN ISO/IEC 17020:2004
Accreditation Scope No.	S103/1
Date of Issue of this Scope	01 September 2011

SCOPE OF ACCREDITATION

Issue No: **S103/1**

Page 1 of 2

INSPECTION BODY

Laboratory Locations

<i>Location Details</i>	<i>Activity</i>	<i>Location Code</i>
Address S&A Quality Assurance Surveyors Ltd., 142 'Matarieh', Nazju Ellul Street, Gzira, GZR 1626, Malta	Office	A

Site activities performed away from the locations listed above

<i>Location Details</i>	<i>Activity</i>	<i>Location Code</i>
Clients	Inspection of Lifts	B



ISO 17020
ACCREDITED
INSPECTION
N° 103

S&A Quality Assurance Surveyors

Scope of Accreditation

SCOPE OF ACCREDITATION

Page 2 of 2

Field of Inspection	Type and Range of inspection	Methods and Procedures	Loc. code
Lifts (as defined in L.N. 231:2007)	The Preventive Inspection of New and Existing Lifts	L.N. 231 of 2007 – Inspection of Lifts Regulations, 2007, Schedule I	B
Lifts (as defined in L.N. 231:2007)	The Thorough Examination of New and Existing Lifts	L.N. 231 of 2007 – Inspection of Lifts Regulations, 2007, Schedule III	B

END OF SCOPE

This scope of accreditation may be revised from time to time by NAB-MALTA. To obtain an up-to-date scope contact NAB-MALTA on +356 21255548 (info@nabmalta.org.mt).

National Accreditation Board - Malta (NAB - MALTA)
2nd Floor Evans Buildings, Merchants Street, Valletta VLT1179 Malta
Tel No. (+356) 21242420; (+356) 21255548 Fax No. (+356) 21242406
Web: www.nabmalta.org.mt - Email: info@nabmalta.org.mt

NAB-MALTA